

Effect of Discharge Fluctuation on Water Quality Variables from the Yeşilırmak River

Ahmet KURUNÇ¹

Kadri YÜREKLI¹

Fazlı ÖZTÜRK²

Geliş Tarihi: 03.01.2005

Abstract: In this study, streamflow and water quality variables including specific conductivity (EC), water temperature, Na^+ , K^+ , $\text{Ca}^{2+}+\text{Mg}^{2+}$, CO_3^{2-} , HCO_3^- , Cl^- , SO_4^{2-} , B, sodium adsorption rate (SAR), hardness and total salt (TS), relationships and hysteresis diagrams were investigated to determine the major processes affecting water quality in the Yeşilırmak River. The base-flow water discharge was observed between July and February whereas March April and May represent a peak as a result of seasonal rainfall, snowmelt and run-off. The results indicate that most variables exhibit clockwise hysteresis with high values during the base-flow and lower values during the high discharge. There is a negative relationship between discharge and water quality variables including EC, Na^+ , K^+ , $\text{Ca}^{2+}+\text{Mg}^{2+}$, HCO_3^- , Cl^- , SO_4^{2-} , SAR, hardness and TS. However, no relationship was obtained between discharge and water temperature, pH, CO_3^{2-} and B. Among the water quality variables EC, $\text{Ca}^{2+}+\text{Mg}^{2+}$, HCO_3^- , SO_4^{2-} , hardness and TS exhibit an open clockwise loop whereas pH, Na^+ , K^+ , Cl^- , CO_3^{2-} , SAR and B exhibit a complex loop. Water temperature was the only variable that exhibits counterclockwise loop.

Key Words: Streamflow, water quality variables, hysteresis, Yeşilırmak River

Debideki Değişimin Yeşilırmak Nehri Su Kalitesi Parametrelerine Etkisi

Öz: Bu çalışmada Yeşilırmak Nehri sularının kalitesini etkileyen esas süreçleri belirlemek amacıyla debi ile su sıcaklığı, Na^+ , K^+ , $\text{Ca}^{2+}+\text{Mg}^{2+}$, CO_3^{2-} , HCO_3^- , Cl^- , SO_4^{2-} , B, sodyum adsorpsiyon oranı (SAR), su sertliği ve toplam tuz (TS) gibi değişik su kalitesi parametreleri arasındaki ilişki ve histerisis diyagramları incelenmektedir. Mevsimsel yağışlar, kar erimesi ve yüzey akış nedeniyle Mart, Nisan ve Mayıs ayları debinin en fazla olduğu dönemi temsil ederken en düşük akım Haziran ve Şubat ayları arasında gözlemlenmiştir. Çalışma sonuçlarına göre su kalitesi parametrelerinin çoğunluğu debinin düşük olduğu dönemlerde yüksek, debinin yüksek olduğu dönemlerde ise düşük değerlere sahip olup saat yelkovanı yönünde histerisisler sergilemektedir. Debi ile EC, Na^+ , K^+ , $\text{Ca}^{2+}+\text{Mg}^{2+}$, HCO_3^- , Cl^- , SO_4^{2-} , SAR, su sertliği ve TS arasında ters yönde bir ilişki bulunmuştur. Buna karşın, debi ile su sıcaklığı, pH, CO_3^{2-} ve B arasında bir ilişki bulunamamıştır. Su kalitesi parametrelerinden pH, Na^+ , K^+ , Cl^- , CO_3^{2-} , SAR ve B karmaşık bir döngüye sahipken EC, $\text{Ca}^{2+}+\text{Mg}^{2+}$, HCO_3^- , SO_4^{2-} , su sertliği ve TS saat yelkovanı yönünde bir döngü göstermektedir. Yalnızca su sıcaklığı saat yelkovanının tersi yönde bir döngü göstermektedir.

Anahtar Kelimeler: Debi, su kalitesi parametreleri, histerisis, Yeşilırmak Nehri

Introduction

The discharge volume of a river is a major factor in understanding the river system. In many rivers, flow will change with time by as much as several orders of magnitude. Since the concentrations of most dissolved constituents in streams decrease during periods of high streamflow and increase during base flow (Anderson et al. 1997, House et al. 1998, Besser and Leib 1999), it is important to characterize seasonal concentration patterns of water quality variables over an entire annual cycle. An understanding of when constituent concentrations are highest, improves the ability of scientist to evaluate the potential changes to the health of aquatic ecosystems and/or usage of water for other purposes. Several years of sample collection often are needed to adequately characterize an annual water-quality cycle because wet, dry, and normal years may have dissimilar water-quality patterns (Leib et al. 2003).

Graphs can communicate complex ideas with clarity, precision and efficiency. They reveal patterns in sets of

data and are often more illustrative than statistical computations. The general objective in graph construction is to concentrate a large amount of quantitative information in a small space so that a comprehensive overview of that information is readily available to the viewer. If discharge is plotted on a time series graph, flood peaks will dominate the discharge scale but will be infrequent on the time scale. Similar features may exist for the concentration of one or more variables in a river, such as suspended sediment concentration. The relationship between concentration of a variable and river discharge can be clearly demonstrated in a plot in which concentration is plotted against flow (Whitfield and Whitley 1986, Whitfield and Clark 1992). A pattern measured in many streams is a tendency for water during a rising stage to have a considerably higher concentration than water passing a sampling point at an equal flow rate after peak discharge has passed (Hem 1985). This condition is referred to as "hysteresis". The concentration-flow pairs are plotted in the order in which they are

¹ Gaziosmanpaşa Üniv. Ziraat Fak. Tarımsal Yapılar ve Sulama Bölümü-Tokat

² Ankara Üniv. Ziraat Fak. Tarımsal Yapılar ve Sulama Bölümü-Ankara

observed and the points are connected in the same order. The hysteresis diagram, showing each data point, indicates that the concentration of a variable can be different when stream discharge is decreasing from what it is at times of increasing discharge.

The present study examines 18 years of water quality and streamflow records from the Yeşilirmak River at Durucasu and describes the processes, which control the quality, and assesses the presence of trend in the record.

Materials and Methods

The Yeşilirmak Basin is one of the twenty-six major basins in Turkey. The water of the river is mostly used for irrigation in addition to drinking, swimming, fishing, wildlife habitat, etc. The river in the basin originates north of Sivas, flows approximately 519 km and reaches to the Black Sea. It drains an area of 38,730 km², which is about 5% of Turkey's surface area. The basin of the river is bounded 39° 30' and 41° 21' N, and 34° 40' and 39° 48' E. The land rises from an altitude of the sea level to 2800 m. In terms of land use, there are about 39% forest regime, 39% cropland and 19% pasture land in the basin. The basin is located on the north Anatolia fault line that is one of the most effective faults in the world and is formed under hercynian, alpine orogeny and epirogeny movement. Therefore, the rock formations on the basin have a broken and curled structure. The rock formation as sandstone, claystone, andesite, volcanic breccia and tuff are common on the area (Anonim 1970).

The headwaters of the river and most of its tributaries originate in the mountains that form the eastern and southern boundaries of the basin. The major tributaries to the Yeşilirmak River are Kelkit, Çekerek, Çorum Çat and Tersakan Streams (Figure 1). Durucasu water quality monitoring station is located about 33 km downstream of city of Amasya. The coordinates of the water quality monitoring station is 40° 44' 40" N and 36° 06' 43" E. The drainage area of the monitoring station is about 21,650 km². Figure 1 shows the location of the Durucasu monitoring station in Yeşilirmak Basin.

The General Directorate of Electric Power Research Survey and Development Administration (EIE) measures




Figure 1. Location map of the monitoring station

water flow (Q) in m³/s, and water quality variables including specific conductivity (EC) in $\mu\text{S cm}^{-1}$, temperature (T) in °C, sodium (Na⁺), potassium (K⁺), calcium+magnesium (Ca²⁺+Mg²⁺), carbonates (CO₃²⁻), bicarbonates (HCO₃⁻), chlorides (Cl⁻), sulfates (SO₄²⁻) and boron (B) in mg L⁻¹ and pH. In addition to these water quality variables, calculated sodium adsorption rate (SAR), hardness in FrSo, and total salt (TS) in mg L⁻¹ are also used in this study. The records for these variables available for the analysis as presented in this paper are on a monthly basis for the period 1970–2001. Since there are many missing values between 1970–1983, the data were examined only for the period 1984 to 2001 (Anonymous 1996).

Time series plots for values of discharge and water quality variables including water temperature, pH, EC, Na⁺, K⁺, Ca²⁺+Mg²⁺, CO₃²⁻, HCO₃⁻, Cl⁻, SO₄²⁻, SAR, hardness and TS from the Yeşilirmak River at Durucasu over 18-year from 1984 to 2001 were prepared. Also trend lines were included in these plots in order to visual examination of trends for each variable. In addition to these plots, the following non-parametric test (Spearman's Rho test) is applied to decide whether trend exists in the monthly data. The Spearman's Rho test recommended by Gibbons (1997) is given as,

$$D_i = U_i - V_i \quad (1)$$

$$R_{sp} = 1 - \frac{6 * \sum D_i^2}{n * (n^2 - 1)} \quad (2)$$

$$t_{cal} = R_{sp} * \left[\frac{(n - 2)}{(1 - R_{sp})^2} \right]^{1/2} \quad (3)$$

Where; D_i is the difference between rank of i^{th} observation in the original time series data (U_i) and rank of i^{th} observation in the time series data arranged in the ascended order (V_i), R_{sp} is the rank order correlation coefficient, n is the number of observations and t_{cal} is the calculated t value. To determine whether there is a trend, the calculated t_{cal} value in Equation 3 should be compared to the t -critical value (± 1.960) from the tables. If the t_{cal} value lies within the 5% significance interval, the data has no trend. The value of the correlation coefficient of rank (Equation 2) is always between -1 and $+1$. The sign of R_{sp} indicates the sign of the slope of the relationship, and the absolute value indicates the strength of the relationship (Gibbons 1997).

Water-quality profiles and hydrographs of discharge for each month averaged over study period were plotted to illustrate seasonal increases or decreases in concentration and to show variation of water quality variables with discharge. Also hysteresis diagrams were prepared to determine the dominant processes affecting the concentrations of the water quality. In order to present relationships between water quality variables and discharge from the Yeşilirmak River at Durucasu, monthly values averaged over 18-year (1984–2001) of each water

quality variables and discharge were used. Similarly, for the hysteresis diagrams, monthly values averaged over 18-year for each of the examined water quality variables were plotted against discharge of the corresponding monthly values averaged over 18-year.

Results and Discussion

Time series of monthly measured values of selected water quality variables at Durucasu water quality monitoring station of the Yeşilirmak River during 18-year period from 1984 to 2001 are presented in Figure 2. The following observations can be stated (Figure 2): many water quality variables showed striking seasonal variations, however, none of these variations seems to be uniform. The reasons for these variations may depend on discharge and seasonality. The magnitudes of the fluctuations in EC, Na⁺, Ca²⁺+Mg²⁺, HCO₃⁻, SO₄²⁻, and TS were much greater than those of concentrations of K⁺ and Cl⁻ and calculated SAR values. Considering the study period of 18-year, values of EC and concentrations of Ca²⁺+Mg²⁺, HCO₃⁻ and TS were relatively stable whereas there were rather slow increase in concentrations of K⁺ and relatively high increase in concentrations of Na⁺, Cl⁻ and SO₄²⁻ and calculated SAR values (Kurunç et al. 2005).

A summary of water-quality and streamflow data for the monitoring station is presented in Table 1. Minimum, maximum, median, and mean values for discharge, water temperature, pH, EC, Na⁺, K⁺, Ca²⁺+Mg²⁺, CO₃²⁻, HCO₃⁻, Cl⁻, SO₄²⁻, SAR, hardness, TS and B were calculated for the station. The ratio of the highest to lowest concentration was very large for HCO₃⁻ (140:1) followed by SO₄²⁻ (13.4:1), Na⁺ (12.6:1), K⁺ (10.8:1) and SAR (8.6:1). There was low ratio for Cl⁻ (6.5:1) and Ca²⁺+Mg²⁺ (4.9:1). The dominant cation and anion in the water of Yeşilirmak River at Durucasu was Ca²⁺+Mg²⁺ and HCO₃⁻, respectively.

Trend analysis is important for determining which portion of a water-quality data set is representative of current conditions. Considering the results of Spearman's Rho test, if a trend was detected for time series of discharge and water quality variables, the direction of trend is given as upward (U) or downward (D) in Table 1. Considering the study period of 18-year, an increased trend was observed for the all water quality variables except water temperature, Ca²⁺+Mg²⁺, HCO₃⁻, hardness and B (no trends), whereas streamflow showed a decreased trend.

The measured values of water quality variables in phase with discharge are shown in Figure 3 for each month averaged over 18-year from 1984 to 2001. Examination of hydrograph in Figure 3 showed that discharge revealed a peak during March April and May. This peak was a result of snowmelt and seasonal rainfall. The plot also revealed a base-flow water discharge between July and February. Among water quality variables, EC, Na⁺, K⁺, Ca²⁺+Mg²⁺, HCO₃⁻, Cl⁻, SO₄²⁻, SAR, hardness, and TS showed a strong seasonal pattern, with a peak occurring between November and February during the lowest discharge. In general, low values of these variables were seen in April and May

during the period of highest discharge. Although EC, Na⁺, Ca²⁺+Mg²⁺, HCO₃⁻, Cl⁻, SO₄²⁻, hardness and TS also peaked in June, recovery to maximum levels was slower than November-February peaks. Sodium adsorption rate also showed a secondary peak between July and August. A different pattern was observed for pH, CO₃²⁻ and B. In general, the lowest values for these variables were observed in March and July, whereas the primary peak was obtained during September and October. As it was expected, the seasonal pattern of water temperature was low during November and March whereas high in June, July and August (Figure 3). In general, there is a negative relationship between the values of all water quality variables (except water temperature, pH, CO₃²⁻ and B) and discharge. That is, as discharge increased the values and concentration of these variables decreased. Major ions from most of the rivers studied by Whitfield and Whitley (1986) exhibited negative relationship with discharge. They claimed that snowmelt and surface run-off, which cause high discharge, dilute groundwater during freshet and, as a result, ion concentration decreases.

As well as suggesting the major processing affecting water chemistry, hysteresis diagrams clearly display the relationship between variables and discharge. Three patterns of hysteresis diagrams were observed. They are open clockwise loops, open counterclockwise loops and complex loops. The hysteresis diagrams for all the analyzed water quality variables were presented in Figure 4 and summarized in Table 2. Williams (1989) stated that if peaks in the major ion concentrations occurred before the discharge peaks, an open clockwise loop is the case. Visual inspection of the hysteresis diagrams for most of the water quality variables including EC, Ca²⁺+Mg²⁺, HCO₃⁻, SO₄²⁻, hardness and TS did indeed show this clockwise loop. Whitfield and Clark (1992) obtained similar hysteresis loops for the major ions. The clockwise hysteresis diagram shows that ion concentration is higher in the pre-freshet period than in the post-freshet period. This is most probably due to greatest amount of dilution occurred during the post-freshet period. Although Na⁺, K⁺, Cl⁻ and SAR showed similar seasonal pattern with EC, Ca²⁺+Mg²⁺, HCO₃⁻, SO₄²⁻, hardness and TS, which were exhibited clockwise rotations, a complex pattern in hysteresis diagrams was observed for these four variables. The fact that one finds variables which exhibit different patterns in one system suggest that the mechanisms which control these variables are different from those that control other variables (Whitfield and Clark 1992). Water temperature was the only variable that exhibit counterclockwise loop (Figure 4 and Table 2).

Conclusion

The result of the hydrologic processes active in the watershed affects the water chemistry of rivers. These seasonal processes cause the variation in water quality parameters. There is significant seasonal variation in the Yeşilirmak watershed. The base-flow water discharge was observed between July and February whereas March April and May represent the high-flow as a result of snowmelt and run-off. Major water quality variables exhibit a negative relationship to discharge, and the pattern of




Figure 2. Time series plots for values of discharge and water quality variables at Durucasu for 18-year from 1984 to 2001




Figure 3. Relationships between water quality variables and discharge at Durucasu for each month averaged over 18-year




Figure 4. Hysteresis diagrams of water quality variables at Durucasu

Table 1. Statistical parameters of the time series of monthly values for water quality variables and discharge at Durucasu

Variable	n	\bar{x}	δ	x_{min}	x_{max}	S	Trend
Discharge (m ³ /s)	216	63.7	42.03	3.72	350.95	60.07	D
Temperature (°C)	216	12.1	12	-2	26	6.13	N
PH	216	8.19	8.24	7.10	10.29	0.41	U
EC (x10 ⁻³ dS m ⁻¹)	216	615.5	602	255	1012	128.96	U
Na ⁺ (mg L ⁻¹)	216	31.93	30.81	4.60	57.93	9.20	U
K ⁺ (mg L ⁻¹)	216	3.92	3.52	1.56	16.81	1.90	U
Ca ²⁺ +Mg ²⁺ (mg L ⁻¹)	216	84.64	84.85	25.92	128.00	17.21	N
CO ₃ (mg L ⁻¹)	216	13.32	12.60	1.80	59.42	10.52	U
HCO ₃ (mg L ⁻¹)	216	254.1	255.5	3.1	427.1	65.63	N
Cl ⁻ (mg L ⁻¹)	216	19.93	19.86	5.67	36.88	5.61	U
SO ₄ ²⁻ (mg L ⁻¹)	216	75.79	72.53	10.57	141.69	25.08	U
SAR	216	0.85	0.85	0.16	1.34	0.20	U
Hardness (FrSo)	216	26.3	26.4	8.1	39.8	5.34	N
TS (mg L ⁻¹)	216	393.9	385	163	648	82.53	U
B (mg L ⁻¹)	216	0.21	0.20	0.03	1.00	0.17	N

Notes: n: sample size, \bar{x} : mean, δ : median, x_{min} : minimum value, x_{max} : maximum value, S: standard deviation, D: downward trend, N: no trend, U: upward trend

Table 2. Patterns of hysteresis in water quality variable-discharge relationship at Durucasu

Relationship to discharge	Clockwise	Counter-clockwise	No pattern
Positive			
	EC		
	Ca ²⁺ +Mg ²⁺		Na ⁺
Negative	TS		K ⁺
	HCO ₃ ⁻		Cl ⁻
	SO ₄ ²⁻		SAR
	Hardness		
None		Temperature	PH
			CO ₃ ²⁻
			B

hysteresis shows a differential snowmelt dilution between in spring and summer. Water temperature, pH, CO₃²⁻ and B were independent of discharge. A complex pattern was observed for pH, CO₃²⁻ and B. Water temperature was the only variable that exhibits counterclockwise loop. Most of water quality variables showed an increased trend whereas streamflow has a decreased trend.

References

Anderson, S. P., W. E. Dietrich, R. Torres, D. R. Montgomery and K. Loague. 1997. Concentration discharge relationships in runoff from a steep, unchanneled catchment. *Water Resources Research* 33 (1): 211–225.

Anonymous, 1996. Water Quality Data for Surface Waters in Turkey, The General Directorate of Electric Power Research Survey and Development Administration (EIE) 96-4, ISBN 975-7566-54-3.

Anonim, 1970. Yeşilirmak Havzası Toprakları. Topraksu Genel Müdürlüğü Yayın No: 241, Ankara.

Besser, J. M. and K. J. Leib. 1999. Modelling frequency of occurrence of toxic concentrations of zinc and copper in the Upper Animas River. Ed. D. W. Morganwalp, H.T. Buxton, U.S. Geological Survey Toxic Substances Hydrology program-Proceedings of the Technical Meeting, Charleston, S. C., March 8–12, 1999: U.S. Geological Survey Water-Resources Investigations Report 99–4018A, p. 75–81.

Gibbons, J. D. 1997. *Nonparametric Methods for Quantitative Analysis*. American Sciences Press, Inc., 537 p., Ohio – USA.

Hem, J. D. 1985. *Study and Interpretation of the Chemical Characteristics of Natural Water*: U.S. Geological Survey Water-Supply Paper 2254, 263 p.

House, W. A. and M. S. Warwick. 1998. Hysteresis of the solute concentrations/discharge relationships in rivers during storms. *Water Research* 32 (8): 2279–2290.

Kurunç, A., K. Yürekli and E. Yurtseven. 2005. Determination of sudden changes in time series of Yeşilirmak River-Durucasu water quality records. *Journal of Applied Sciences* 5 (1): 122–126.

Leib, K. J., M. A. Mast and W. G. Wright. 2003. *Using Water-Quality Profiles to Characterize Seasonal Water Quality and Loading in the Upper Animas River Basin, Southwestern Colorado*. U.S. Geological Survey Water-Resources Investigations Report 02–4230, 46 p.

Whitfield, P. H. and M. J. R. Clark. 1992. *Patterns in Water Quality in the Rocky Mountains of British Columbia*. Ed. J.H.M. Willison, S. Bondrup-Neilsen, C. Drysdale, T.B. Herman, N. W. P. Munro and T. L. Pollock, *Science and the Management of Protected Areas*, p. 391–409. Elsevier, New York.

Whitfield, P. H. and W. G. Whitley. 1986. *Water Quality-Discharge Relationships in the Yukon River Basin, Canada*. *Cold Regions Hydrology Symposium*. American Water Resources Association 149–156.

Williams, G. P. 1989. Sediment concentration versus water discharge during single hydrologic events in rivers. *Journal of Hydrology* 111 (1): 89–106.

İletişim adresi:

Ahmet KURUNÇ
 Gaziosmanpaşa Üniversitesi Ziraat Fakültesi
 Tarımsal Yapılar ve Sulama Bölümü 60250 Taşlıçiftlik-Tokat
 Tel: 0 356 252 14 79 (ext:2245)
 e-posta: akurunç@yahoo.com